

Sanctioned Interpretations to e-Stewards Standard 4.1

1. **Description:** *Amendment to battery load testing requirements*

Section: 8.5.1 b) 2) i. E

Proposed change:

E. In instances where an accurate smart chip read cannot be determined, conduct a 10-minute load test using the Prime95 program at the -t setting option or an equal or greater load.

Reason: A study was presented to BAN indicating that the SmartChip read during testing was successful 99.98% of the time at accurately depicting the battery capacity, and thus a load test was inefficient and not necessary.

Outcome: Approved by majority quorum of e-Stewards Processors